

OEKOMARK PRO

MODE D'EMPLOI

Lavage de 60°C à 85°C

	Température	190 °C
	Temps de pose.....	30 secondes
	Pression.....	forte (4 bars)
	Démoulage.....	à froid

Ces valeurs sont données à titre indicatif : effectuer toujours des tests avant de lancer une production.

L'oekostretch n'adhère pas sur les fibres nylon fortement imperméabilisées .

CONSEILS

- L'OEKOMARK PRO n'adhère pas sur les textiles enduits, en particulier les fibres nylon
- Tendre les vêtements pour éviter les faux plis et les surépaisseurs (boutons, bas de maillots, coutures de manches, cols, autres logos...)
- Enfiler les vêtements dans les jeannettes
- Re-presser le transfert quelques secondes après démoulage

monblason

Heat transfer solutions / Since 1906

OEKOMARK PRO

INSTRUCTIONS

Washable from 60°C to 85°C

	Temperature	190 °C
	Pressing time.....	30 seconds
	Pressure.....	strong (4 bars)
	Peeling.....	cold

These settings are given for guidance : always give a try before strating a production. Oekostretch does not stick on strongly waterproof nylon.

ADVICES

- Cannot be ironed directly (ironed the garment inside out)
- Correctly stretch the garment to avoid folds and thicknesses (mind buttons, tee-shirt edges, sleeve sewings, neckband, other logos...)
- Slip on the garment using the press table
- Press again the printing few seconds after the first heat pressing
- This product is not suitable for nylon fiber or coated garments.

www.monblason.com

