

JET PRINT

MODE D'EMPLOI

Lavage 60°C max

	Température.....	150 °C
	Temps de pose.....	15 secondes
	Pression.....	moyenne (3-4 bars)
	Démoulage.....	à chaud

Ces valeurs sont données à titre indicatif : effectuer toujours des tests avant de lancer une production.

Le SERI-STRETCH n'adhère pas sur les tissus enduits ou les mailles ajourées.

CONSEILS

- Ne pas repasser directement (vêtement à l'envers)
- Tendre les vêtements pour éviter les faux plis et les surépaisseurs (boutons, bas de maillots, coutures de manches, cols, autres logos...)
- Enfiler les vêtements dans les jeannettes
- Fibre nouvelle : procéder à des essais ou nous consulter
- Nettoyage à sec : non recommandé



monblason

Heat transfer solutions / Since 1906

JET PRINT

INSTRUCTIONS

Washable up to 60°C

	Temperature.....	150 °C
	Pressing time.....	15 seconds
	Pressure.....	middle (3-4 bars)
	Peeling.....	hot

These settings are given for guidance : always give a try before strating a production.
SERI-STRETCH does not stick on coated fabrics or openwork meshes.

ADVICES

- Cannot be ironed directly (ironed the garment inside out)
- Correctly stretch the garment to avoid folds and thicknesses (mind buttons, tee-shirt edges, sleeve sewings, neckband, other logos...)
- Slip on the garment using the press table
- Unknown fiber : do a test or contact us
- Dry cleaning is not recommended

www.monblason.com

